

EQUIPMENT CONDITION REPORT

Equipment Number:	103888	Declared Value:	\$1,500
Year:	1999		
Description:	Chevy Silverado 1500/green VIN#: 1GCEC14T1XEL33616		
<input checked="" type="radio"/> GAS / DIESEL / ELECTRIC	* 1 Accident History Reported: Broken Window (repaired)		
Mileage/Hours:	151,544	Broken Window (repaired)	
Disposal #:	F92437		

For each item identified below, circle the number to the right that best fits your judgment of its quality. Use the rating scale to select the quality number.

	Scale					Excellent
	Poor	Good				
1. Appearance	1	2	3	4	5	
2. Mechanical	1	2	3	4	5	
3. Engine (RUNS / INOP)	1	2	3	4	5	
4. Transmission (AUTO / MANUAL)	1	2	3	4	5	
5. Steering	1	2	3	4	5	
6. Brakes	1	2	3	4	5	
7. Tires	1	2	3	4	5	
8. Paint	1	2	3	4	5	
9. Glass (BROKE / PITTED / SCRATCHED)	1	2	3	4	5	
10. Interior	1	2	3	4	5	
11. Body	1	2	3	4	5	
12. Rust	1	2	3	4	5	
13. Accessories	1	2	3	4	5	

flat tire (will air up)

Ø

Ø