

## EQUIPMENT CONDITION REPORT

|  |                                |
|--|--------------------------------|
| Equipment Number: <b>T03883</b>                          | Declared Value: <b>\$1,500</b> |
| Year: <b>1999</b>  |                                |
| Description: <b>Chevy Silverado 1500</b>                 | VIN#: <b>1GGEC14T1XE235110</b> |
| <input checked="" type="radio"/> GAS / DIESEL / ELECTRIC | <b>*NO Accidents Reported</b>  |
| Mileage/Hours: <b>145708</b>                             |                                |
| Disposal #: <b>F92438</b>                                |                                |

For each item identified below, circle the number to the right that best fits your judgment of its quality. Use the rating scale to select the quality number.

|                                       | Scale |                                    |                                    |                                    |   |
|---------------------------------------|-------|------------------------------------|------------------------------------|------------------------------------|---|
|                                       | 1     | 2                                  | 3                                  | 4                                  | 5 |
| <b>CONDITION</b>                      | P     | O                                  | O                                  | G                                  | E |
|                                       | 1     | 2                                  | 3                                  | 4                                  | 5 |
| 1. Appearance                         | 1     | 2                                  | <input checked="" type="radio"/> 3 | 4                                  | 5 |
| 2. Mechanical                         | 1     | 2                                  | <input checked="" type="radio"/> 3 | 4                                  | 5 |
| 3. Engine (RUNS / INOP)               | 1     | 2                                  | 3                                  | 4                                  | 5 |
| 4. Transmission (AUTO / MANUAL)       | 1     | 2                                  | 3                                  | 4                                  | 5 |
| 5. Steering                           | 1     | 2                                  | 3                                  | <input checked="" type="radio"/> 4 | 5 |
| 6. Brakes                             | 1     | 2                                  | <input checked="" type="radio"/> 3 | 4                                  | 5 |
| 7. Tires                              | 1     | 2                                  | 3                                  | 4                                  | 5 |
| 8. Paint                              | 1     | 2                                  | <input checked="" type="radio"/> 3 | 4                                  | 5 |
| 9. Glass (BROKE / PITTED / SCRATCHED) | 1     | 2                                  | 3                                  | 4                                  | 5 |
| 10. Interior                          | 1     | <input checked="" type="radio"/> 2 | 3                                  | 4                                  | 5 |
| 11. Body                              | 1     | 2                                  | <input checked="" type="radio"/> 3 | 4                                  | 5 |
| 12. Rust                              | 1     | 2                                  | 3                                  | 4                                  | 5 |
| 13. Accessories                       | 1     | 2                                  | 3                                  | 4                                  | 5 |

Needs Tires (will air up for you)

Dent on back right side of the Bed

Ø